

Picote Brush Coating™ Starter Package

A recommended list of supplies to get started with the Picote Brush Coating™ System.

*If your customer is purchasing this system for a specific job, be sure to make adjustments accordingly.

All pipes must be properly cleaned before coating. Please ask about a drain cleaning package.

* For Brushes, refer to the Brush Sizing Guide to determine which sizes will best suit your customers needs.

Mini Coating System (1 1/4" to 6" pipes)

QUANTITY	ITEM	QUANTITY	ITEM
1 [Mini Coating Pump	1 pk	Supply Hose
1 [] Mini Miller (2''-6'')	1 pk	Resin Cup
1 [Mini Cleaner (1 1/4" -3")	1	Smart Mixer 2.0
3 🗌	Dual Color Epoxy Kits	2	☐ 10mm Hose Clamp
3 sets	Brushes* 1set= (front+back)	2	13mm Hose clamp
1 roll	Delivery Hose	1	Delivery Hose Lube
		1	Hex Keys (2.5, 3, 5)

Maxi Coating System (3" to 12" pipes)

QUANTITY	ITEM	QUANTITY ITEM
1 [Maxi Coating Pump (3" to 12" pipes)	1 Smart Mixer 2.0 3 16mm Hose Clamps
1 [¬ ' '	1 Delivery Hose Lube
6	Dual Color Epoxy Kits	1 roll Delivery Hose
4	Brushes*	1 Hex Keys (3, 4, 5)
2 🗆	Brush Stoppers	

The Picote Heater is a great addition to both coating systems. Use it to speed up cure times. (comes with 16ft/5m hose)

PICOTE

Additional Items Needed for Operation:

CCTV Camera	Gloves	Scissor Style Tubing Cutter	7mm Nut Driver
Mini Camera for small diameter	Acetone	Temp Gun	Heat Gun/butane torch
Silicone Grease	Duct Tape	Rags	

